

# Calorimeter High Voltage

- Yimei pointed out calorimeter HV info out-of-date; this is my correction
- Amalgam of web info from Simone dell'Agnello (5/01) and ace talk I gave (12/01) and new info
- Players:
  - Fermilab: Steve Hahn (CEM, xenon, HV, iFIX), Nikolay Luzhetskiy (HV, iFIX)
  - Argonne: Larry Nodulman (SPL), Bob Wagner (CEM, HV)
  - U. of Rochester: Willis Sakamoto (SPL), Howard Budd (plug, HV)
  - UCLA: Mike Lindgren, Alon Attal (plug, HV)
  - Frascati, INFN: Marco Cordelli, Simone dell'Agnello, Fabio Happacher, Stefano Miscetti, Fotis Ptohos, Andrea Sansoni (CHA, WHA, HV, iFIX)
  - Bologna, INFN: Luciana Malferrari, Stefano Zuchelli (plug, HV, iFIX)
  - ITEP: Konstantin Kotelnikov, Irina Schreiber (HV, iFIX)
- First the summary, then the details!




# Calorimeter High Voltage

- CEM (central E-M), CHA (central hadron), WHA (wall hadron):
  - HV for arches and walls generated in Gamma HV supplies on 1st floor. Voltage divider on back of Gamma provides readback and fast trigger inhibit via APACS and CDFS5 in cryo area
  - Distributed via "daisy chain" to Pisaboxes in one arch or one wall
  - Pisabox distributes, sets, and reads HV for each phototube in one central wedge or several endwall modules; controlled from PISABOX on 1st floor
  - CEM xenon flashers (one per wedge) also need HV, supplied from two CAEN 127s on 1st floor; also controlled by PISABOX

- PEM (plug E-M), PHA (plug hadron), PES (plug strip):
  - HV for two "PMT boxes" generated and distributed to phototubes by CAEN 527 mounted on plug fixture; set and read via CDFEPHV on 3rd floor. Status output provides fast trigger inhibit.



# Calorimeter High Voltage





### 🗲 Central Calorimeter HV Distribution 🗡






- Gamma HV bulk power supplies
  - Up to 2000 V @ 100 mA each
  - Two racks on 1st floor
  - HV racks tripped if flammable gas alarm
  - Voltage dividers on back provide remote readout to APACS chassis via node CDFS5
- Pisabox (on wedges and walls)
  - HV distribution only
  - Chassis with three boards: top two HV distribution boards (20 channels each), bottom microprocessor board
  - HV boards "daisy chain" HV via HV inputs on left; processor boards "daisy chain" CAEN serial via LEMO cables
  - HV set with potentiometers connected to motors
  - HV readback via slow ADC—0.5 sec/channel



### Central Calorimeter HV Distribution







## Central Calorimeter HV Distribution //


Steve Hahn Calorimeter HV 02/10/2003

#### **EAST CENTRAL ARCHES**

(LOOKING WEST)









# Gamma HV Monitoring

Steve Hahn Calorimeter HV 02/10/2003

:02:00 PM 2/10/03	GAMMA VOLTAGE SOURCES				CLOSE
DEVICE	DESCRIPTION	LO LIMITS	CURRENT VALUES	HI LIMITS	Audible Alarm
CSX NW	Voltage Indication Current Indication	2122 -2	2127 V -0 mA	2132 5	( <b>(</b> )1
csx sw	Voltage Indication Current Indication	2113 10	2118 V 69 mA	2123 72	( <b>(</b> )1
CSX NE	Voltage Indication Current Indication	1974 10	1991 V 61 mA	2003 72	<b>(</b> (3)1
CSX SE	Voltage Indication Current Indication	2135 10	2140 V 61 mA	2145 72	( <b>(</b> )1
CEM NW ARCH	Voltage Indication Current Indication	1240 10	1246 V 51 mA	1250 72	( <b>(</b> )1
CHA NW ARCH	Voltage Indication Current Indication	1727 10	1733 ∨ 62 mA	1737 72	( <b>(</b> )a
CEM SW ARCH	Voltage Indication Current Indication	1243 10	1248 ∨ 49 mA	1253 72	( <b>(</b> )n
CHA SW ARCH	Voltage Indication Current Indication	1746 -2	1751 ∨ -0 mA	1756 72	( <b>(</b> )1
CEM NE ARCH	Voltage Indication Current Indication	1279 10	1286 √ 49 mA	1289 72	( <b>(</b> )
CHA NE ARCH	Voltage Indication Current Indication	1724 -2	1727 ∨ -0 mA	1733 72	( <b>(</b> )1
CEM SE ARCH	Voltage Indication Current Indication	1234 10	1240 V 47 mA	1244 72	( <b>(</b> )
CHA SE ARCH	Voltage Indication Current Indication	1729 -2	1734 V -0 mA	1739 72	( <b>(</b> )1
CSP NORTH	Voltage Indication Current Indication Voltage Indication	2112 10 2113	2120 V 60 mA 2121 V	2122 72	<b>(</b> ( <b>)</b> 1
CSP SOUTH	Current Indication  Voltage Indication	2113 10 -2	68 mA -0 V	2133 72	<b>()</b> 1
SVX INCHWORM	Current Indication	-2 -2 1916	-0 V -0 mA 1919 V	8 5	( <b>()</b> 1
MINISKIRT ARCH	Current Indication  Voltage Indication	10	38 mA	1926 72 1075	( <b>()</b> 1
WHA 1	Current Indication Voltage Indication	10 10 1186	40mA	72 1196	( <b>()</b> II
WHA 3	Current Indication  Voltage Indication	10 1286	54 mA 1290 V	72 1296	(13a (13a
MIMO	Current Indication Voltage Indication	-2 1307	-0 <sub>mA</sub>	72	( <b>()</b> 1


#### Gamma HV readout

- Runs on CDFS5, <u>not</u> any longer on PISABOX
- Main CDF menu (click on any CDF logo) → Misc. menu → Gamma (same color as global alarm box)
- ➤ Updates @ 30 Hz
- Any Gamma outside limits of ±5 V from nominal generates trigger inhibit, audible alarm, GAM global alarm box turns red, and current value on this display turns red



# Calorimeter PMT HV Monitoring

Steve Hahn Calorimeter HV 02/10/2003



#### PISABOX PMT readout

- Takes 25 minutes to readout sequentially CHA CEM WHA, then waits 2 hours to cycle
- If PMTs out of range, bars and global alarm boxes will go yellow (±3 V) or red (±5 V) and slow trigger inhibit will occur
- Clicking "D" on global alarm box will bring up DBANA-like map of all PMT voltage deviations
- If bars deviate from 100% noticeably but no alarm, notify experts
- HV control by experts only, normally always on



## PISABOX iFIX node

- Pisabox computer on 1st floor controls two processes:
  - Pisabox PMT readout (every 2 hours)
  - Xenon HV control and readout (during CEM xenon calibration only)
- Unfortunately, CAMAC accesses between Xenon HV process and Pisabox/Gamma readout processes causes errors
  - Must kill Pisabox readout before ramping up Xenon HV. Note CEM CHA WHA GAM bars on high voltage display will eventually all go gray.
  - ➤ Must log out and back in to Pisabox account to restart Pisabox and Gamma readouts. This is VERY IMPORTANT! If you do not, you will no longer be monitoring PMT HV status. Starts reading PMT HVs immediately, so gray bars should turn green within 1/2 hour.

### Xenon HV Distribution and Control





- Xenon HV (2850 V to each xenon flasher box on each wedge)
  - Two CAEN SY127s above PISABOX computer
  - Should see activity on front panel while ramping HV up or down
  - Readout via CAEN SY127 CAMAC interface (as are Pisaboxes in CAMAC crate below computer) and CAMAC Jorway interface in PISABOX computer



### Xenon HV Instructions

Steve Hahn Calorimeter HV 02/10/2003

#### **Xenon HV instructions:**

- Go to the Pisabox PC in 1RR06C; it should be running and logged into the CDF-PISABOX account (this is the PC user account, not the iFIX login).
   You will need to know the password for this account; if you do not, contact the operations manager to get it.
- If the workstation is locked, unlock it and enter the username (it should come up with CDF-PISABOX as the default) and password.
- Kill the PMT HV readout process. There should be a window named C:\PB\PBHVOUT\PB\_V6.EXE; close (not minimize) this window to kill the process. Note that while the PMT HV process is not running, the CEM, CHA, WHA, and GAM HVs on the iFIX "High Voltage Summary" will eventually go to zero.
- Start the "Xenon HV" process. If you do not see it, start it up by doubleclicking on the "Xenon HV" icon on the desktop.



## Xenon HV Instructions

- Maximize the "Intellution iFIX WorkSpace" if it is minimized. If there is no "Intellution iFIX WorkSpace" process, start it from the "Start" menu: Programs -> iFIX -> Intellution iFIX WorkSpace. Click on the "OPEN" item in the "FILE" menu. Assuming you are starting from the S:/dynamics/Pic folder, open the "Cdfmcs" folder, then open the "MUON" folder. Doubleclick on the file "Xenon Flashers". The "Xenon Flashers" HV display should appear.
- Turn on all the xenon flashers:
  - ➤ First try just clicking on the "All Flashers" button, and then the "ON" button to turn on all xenon flashers' HVs. If all 48 wedges ramp up to green (full HV) after two minutes, you are done.
  - ➤ If nothing happens or only a few wedges turn on, you may have to turn on each arch individually. Click one at a time on the "SE", "NE", "SW", "NW" buttons and then the "ON" button. Remember to unclick the previous arch's button before preceding to the next arch.
  - Some individual wedges may need special attention. See special instructions at end of this procedure for any such cases.
- Run the CEM xenon flasher calibration with RUN\_CONTROL.



## Xenon HV Instructions

Steve Hahn Calorimeter HV 02/10/2003

- When you are done, turn all xenon flasher HVs off. Click "All Flashers" (if it is not already selected) and then "OFF". When all wedges have turned black (HV off), "CLOSE" the xenon flasher display.
- When you are done, turn all xenon flasher HVs off. Click "All Flashers" (if it is not already selected) and then "OFF". When all wedges have turned black (HV off), either minimize or close the "Intellution iFIX Workspace" and close (not minimize) the "Xenon HV" window to kill this process.
- Now restart the PMT HV readout process by double-clicking the "PMT HV" shortcut icon on the desktop. It may take up to half an hour for the CEM CHA WHA HV bars to reappear on the HV summary.
- Special instructions for individual wedges (click on the individual wedge in the xenon flasher display; click "OK" when done):
  - ➤ 17E may require you to turn it on or off individually. However, it seems to ramp on or off correctly after doing this.
  - ➤ 23E has been deliberately set to 2861 V instead of the usual 2850 V. It may end in a "software undervoltage" state with the voltage at 2845 V. This should be OK. The suspicion is that the CAEN readback is not working correctly for this channel.

15